

FIG. 1






FIG. 2






BUR920040156US1

FIG. 3



3/7

FIG. 4



4/7

FIG. 5





FIG. 6



6/7


FIG. 7

700 Distinction Between Insulator
600 and Hardmask 200

Insulator 600

Residual 200
Hardmask

No Erosion
or Corner
Rounding



7/7
FIG. 8

